

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2024

Submitted Date:

11/07/2024

Document Number:

717700645

FIELD INSPECTION FORM

Loc ID 458676 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10518
Name of Operator: CONFLUENCE DJ LLC
Address: 1401 WYNKOOP STREET STE 120
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gale, Justin		jpgale@confluencelp.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Rothe, Brittany		brothe@confluencelp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458679	WELL	DG	03/02/2020	LO	123-48438	SILVERTON 5-4-3L	DG

General Comment:

[This is an audit on the well](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	No Wellhead sign		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 458679 Type: WELL API Number: 123-48438 Status: DG Insp. Status: DG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A. Surface Casing has been drilled. Form 5 was received on 4/23/2020
 Confluence has suspended drilling operations in order to evaluate the economic viability of horizontal development in this area prior to continuing the Silverton program. The anticipated date of resumption of drilling is TBD pending the results of Confluence's economic analysis. Confluence will comply with all bradenhead and MIT testing requirements during the suspension of operations.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____

Comment: No updated annual BH test on file 12/20/2024

Corrective Action: Submit reports as per Rule 419. Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday, November 5, 2024, at approximately 10:47 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Well: Silverton 5-4-3L Operator: Confluence DJ LLC API #05-123-48438 County: Weld</p> <p>During the inspection, a producing well was observed. The following possible compliance issues were identified: No updated annual BH test on file. Submit reports as per Rule 419. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	11/07/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403986855	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6777895
717700646	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6777853