

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403996328

Date Received:
11/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 7125

Name of Operator: BEEMAN OIL & GAS INC

Address: 13635 E 104TH AVENUE STE 400

City: COMMERCE CITY State: CO Zip: 80022

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

cassyswasey@gmail.com

dnr_cogccenforcement@state.co.us

jspconcrete@yahoo.com

logan.maxwell@state.co.us

denise.arthur@state.co.us

[Maxwell, Logan](#)

[Arthur, Denise](#)

[Lawton, Lisa](#)

[970-846-4639](tel:970-846-4639)

lisa@beemanoil.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696206205

Inspection Date: 08/22/2024

FIR Submit Date: 09/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BEEMAN OIL & GAS INC

Company Number: 7125

Address: 13635 E 104TH AVENUE STE 400

City: COMMERCE CITY State: CO Zip: 80022

LOCATION - Location ID: 425419

Location Name: Bret Grandbouche Number: 24-02H County: _____

Qtrqtr: SESW Sec: 2 Twp: 6N Range: 92W Meridian: 6

Latitude: 40.494389 Longitude: -107.689272

FACILITY - API Number: 05-081- -00 Facility ID: 425419

Facility Name: Bret Grandbouche Number: 24-02H

Qtrqtr: SESW Sec: 2 Twp: 6N Range: 92W Meridian: 6

Latitude: 40.494389 Longitude: -107.689272

CORRECTIVE ACTIONS:

1 CA# 198489

Corrective Action: Install/replace guard on pumpjack wheel.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/10/2024

Operator
Comment:

replace guard

ECMC Decision:

ECMC
Representative:

2 CA# 198490

Corrective Action: Comply with Rules 1002.c and 1002.f and implement BMPs to protect the stockpile from erosion, degradation, sediment transport and weed establishment.

If the stockpiled materials are not necessary, materials require removal pursuant to Rule 606.a.

Date: 09/16/2024

Response: CA COMPLETED

Date of Completion: 11/15/2024

Operator
Comment:

Beeman Oil is actively working on this

ECMC Decision:

ECMC
Representative:

3 CA# 198491

Corrective Action: Comply with Rule 606.

Date: 01/01/1111

Response: CA COMPLETED

Date of Completion: 10/08/2024

Operator
Comment:

all debris has been removed

ECMC Decision:

ECMC
Representative:

4 CA# 198492

Corrective Action: Implement signage to identify contents within container, pursuant to 605 Requirements.

Date: 10/09/2024

Response: CA COMPLETED

Date of Completion: 11/15/2024

Operator
Comment:

signage added

ECMC Decision:

ECMC
Representative:

5 CA# 198493

Corrective Action: Comply with Rule 605.h

Date: 10/09/2024

Response: CA COMPLETED

Date of Completion: 11/10/2024

Operator
Comment:

signage placed

ECMC Decision: _____

ECMC
Representative:

6 CA# 198494

Corrective Action: Comply with Rule 603.i and replace cap/plug at tank(s).

Date: 09/16/2024

Response: CA COMPLETED

Date of Completion: 10/08/2024

Operator
Comment: replaced cap

ECMC Decision: _____

ECMC
Representative:

7 CA# 198495

Corrective Action: See "COGCC Comments" for corrective actions at the end of this report.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/15/2024

Operator
Comment: Beeman Oil is establishing a weed management plan for this location. It will be submitted directly to Thomas Hoak per his direction. The location will be reseeded in early spring 2025 and covered in mulch. New BMPS will be in place to stop erosion and sediment movement.

ECMC Decision: _____

ECMC
Representative:

8 CA# 198496

Corrective Action: See "COGCC Comments" for corrective actions at the end of this report.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/15/2024

Operator
Comment: Beeman Oil is establishing a weed management plan for this location. It will be submitted directly to Thomas Hoak per his direction. The location will be reseeded in early spring 2025 and covered in mulch. New BMPS will be in place to stop erosion and sediment movement.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Per Thomas Hoak - a weed management plan will be submitted to him directly to take care of the noxious weed issue

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lisa Lawton

Signed: _____

Title: agent

Date: 11/15/2024 11:28:13 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403996382	Cap replaced
403996389	Guard replaced
403996390	Propane label
403996391	Signage
403996394	Tank Labels
403996395	Tank Labels

Total Attach: 6 Files