

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404000756

Date Received:

11/20/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708303050

Inspection Date: 11/08/2024

FIR Submit Date: 11/12/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**LOCATION - Location ID: 334628**

Location Name: PA-67S95W Number: 6NENW County: \_\_\_\_\_

Qtrqtr: NENW Sec: 6 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.471923 Longitude: -108.043984

**FACILITY - API Number: 05-045- -00 Facility ID: 334628**

Facility Name: PA-67S95W Number: 6NENW

Qtrqtr: NENW Sec: 6 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.471923 Longitude: -108.043984

**CORRECTIVE ACTIONS:**

1 CA# 200391

Corrective Action: Cover wellhead cellars. 602.c: Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.

Date: 08/08/2024

Response: CA COMPLETED

Date of Completion: 11/14/2024

Operator  
Comment:

Bunny boards have been installed within each of the shallow well cellars. There is a perimeter fence installed around the wellheads to keep unauthorized personnel out of this area. This corrective action is complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Bunny boards have been installed within each of the shallow well cellars. There is a perimeter fence installed around the wellheads to keep unauthorized personnel out of this area. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 11/20/2024 10:50:19 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404000756	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files