

**COLORADO OIL & GAS CONSERVATION COMMIS
FIELD INSPECTION REPORT**



00032589

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	<div style="font-size: 2em; color: red; border: 1px solid red; border-radius: 50%; width: 40px; height: 40px; display: flex; align-items: center; justify-content: center; margin: 0 auto;">C</div> 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- 123 - 8861	LEASE NAME: CHAMPLIN 42-4 #4
LOCATION: SE NE 4 IN 68W	OPERATOR: UPRC
DATE: 2/12/96	INSPECTOR: SHELTON
Insp. Type: 1D	Insp. Status: TA
PA: Y N	Pass/Fail: P (F)
	Viol.: (Y) N
	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	OK	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	PUMP JACK, RODS, TBG, REMOVED / FLOWLINE INTACT	

CORRECTIVE ACTION REQUIRED:	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.