

State of Colorado
Oil and Gas Conservation Commission
DEPARTMENT OF NATURAL RESOURCES

WELL ABANDONMENT REPORT

This form is to be submitted as an intent whenever a plugging is planned on a borehole. The approved intent shall be valid for one year after the approval date; after that period a new intent will be required. After the plugging is complete, this form shall again be submitted as a subsequent report of the work as actually completed.

OGCC Operator Number: 41385
Name of Operator: HS Resources
Address: 3939 Carson Avenue
City: Evans State: Co. Zip: 80620
API Number: 05- 123-09542
Well Name: Futura Horse Farms Village 41-03 Number: 4
Location (QtrQtr, Sec, Twp, Rng, Meridian): SENE 3 1N 68W
County: Weld Federal, Indian or State lease number:
Field Name: Spindle Field Number: 77900

Contact Name & Phone

Elaine Rivas

No: 970-330-0614

Fax: 970-330-0431

ET ☒ OE ☒ PR ☒ ES ☒

24 hour notice required, contact

@

Complete the
Attachment Checklist

Oper OGCC

Wellbore Diagram

Cement Job Summary

Wireline Job Summary

☐ Notice of Intent to Abandon☒

Subsequent Report of Abandonment

Background for Intent Only

Reason for abandonment: ☐ Dry ☒ Production Sub-economic ☐ Mechanical Problems ☐ Other
Casing to be pulled: ☐ No ☒ Yes Top of casing cement:
Fish in hole: ☒ No ☐ Yes If yes, explain details below:
Wellbore has uncemented casing leaks: ☒ No ☐ Yes If yes, explain details below:
Details:

Current and Previously Abandoned Zones

Formation	Perforations	Date	Method of Isolation (None, Squeezed, BP, Cement, etc.)	Plug Depth
Sussex	4654-4694			

Casing History

Casing String	Size	Cement Top	Stage Cement Top
Surface	8 5/8		
Production	4 1/2		

Plugging Procedure for Intent and Subsequent Report

1. CIBP #1 Depth 4604' CIBP #2 Depth CIBP #3 Depth NOTE: Two (2) sacks cement required on all CIBPs
2. Set _____ sks cmt from _____ ft. to _____ ft. in ☐ Casing ☐ Open Hole ☐ Annulus
3. Set _____ sks cmt from _____ ft. to _____ ft. in ☐ Casing ☐ Open Hole ☐ Annulus
4. Set _____ sks cmt from _____ ft. to _____ ft. in ☐ Casing ☐ Open Hole ☐ Annulus
5. Set _____ sks cmt from _____ ft. to _____ ft. in ☐ Casing ☐ Open Hole ☐ Annulus
6. Set _____ sks cmt from _____ ft. to _____ ft. in ☐ Casing ☐ Open Hole ☐ Annulus
7. Perforate and squeeze @ _____ ft. with _____ SKS Leave at least 100 ft. in casing
8. Perforate and squeeze @ _____ ft. with _____ SKS Leave at least 100 ft. in casing
9. Perforate and squeeze @ _____ ft. with _____ SKS Leave at least 100 ft. in casing
10. Set 70 SKS 1/2 in 1/2 out surface casing from 898' ft. to 698' ft.
11. Set 10 SKS @ surface
- Cut 4 feet below ground level, weld on plate Dry-Hole Marker ☒ No ☐ Yes
- Set na SKS in rate hole Set na SKS in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing recovered: 4173' ft. of 4 1/2 in. casing Plugging date: 7-9-99

*Wireline contractor: ADI of Fort Morgan, Colorado

*Cementing contractor: H&R Well Service of Fort Morgan, Colorado 970-867-9007

Type of cement and additives used: Class G Neat

*Attach job summaries.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name Harlan Hodge

Signed Harlan Hodge Title: P&A Manager/H&R Date: 7-9-99OGCC Approved: JD Title: Date: 7/23/99

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL

H & R WELL SERVICES, INC.

0902 Road 4
WIGGINS, COLORADO 80654

(970) 432-5285 (303) 654-1600

TO

HS Resources

Evans, Colorado

THE FOLLOWING WAS NOTED:

> MIRU and lay down rods and tubing

SET CIBP at 4604, cap with 2 sks

Free point, cut and lay down casing from 4173'

TIH with tubing to 898'

Pump 70 sks from 898' to 698'

TOH


Pump 10 sks at surface

Dig out and cut off well head

Weld on plate

Harlan Hodge, P&A Manager/H&R Well Service

DATE 7-9-99		JOB NO.	
PROJECT			
LOCATION Futura Horse Farms # 4			
CONTRACTOR		OWNER	
WEATHER		TEMP. ° at AM ° at PM	
PRESENT AT SITE			
JUL 19 1999			
OIL & GAS CONS. COMM.			



OK JH


ORIGINAL

FIELD REPORT

COPIES TO

SIGNED

[Signature]

JUL 19 1999

FIELD SPINDLE

WELL NAME/No. Furner Lbese Village #4		STATE CA
COUNTY WELD	CITY Greeley	

079906-

SIGNATURE OF CUSTOMER OR AUTHORIZED REPRESENTATIVE

DATE	TIME
------	------

UNIT NUMBER <u>202</u>		UNIT NUMBER	
CREW NAMES	EMPLOYEE NO.	CREW NAMES	EMPLOYEE NO.
ENGR. <u>A</u>		ENGR.	
OPER. <u>M</u>		OPER.	
OPER.		OPER.	