

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2024

Submitted Date:

11/19/2024

Document Number:

714300142

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Findings:
6 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488153	SPILL OR RELEASE	CL			-	Rasmussen 36-29 Flowline	EI
488157	SPILL OR RELEASE	CL	10/04/2024		-	Rasmussen Federal 35-29 Flowline	EI

General Comment:
 This is an environmental inspection to determine progress on Spill ID 488157/ Remediation Project No 28944 & Spill ID 488153/ Remediation Project No 33723. Any corrective actions from previous inspections that have not been addressed are still applicable.
 There were no operator or contract environmental personnel on location at the time of this field inspection.
 Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type			
Comment:	Fencing around the excavations are inadequate. Fencing has fallen around some areas of the excavations.		
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v	Date:	12/03/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 488153 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488157 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Multiple excavations open on location. No environmental impacts were visible in-situ and no groundwater was observed in the open excavation. Form 27 Document No 403955204 In Process for remediation#28944; Form 27 Document No 403968383 In Process for remediation#33723. Operator will comply with the implementation schedule and Conditions of Approval for all remaining remediation of soil impacts, reclamation and reporting established in the ECMC Remediation Project No. 28944 & 33723..

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Comment	Multiple soil stockpiles noted on location. All soil stockpiles were unmarked and unlined. Some soil stockpiles had inadequate storm water BMPs.		
Corrective Action	If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure. Install or repair required BMPs per Rule 1002.f.(2)C.		Date: <u>12/03/2024</u>

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403999461	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792241
714300143	Insp Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6792223