

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404010743

Date Received:

11/29/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201749

Inspection Date: 10/25/2024

FIR Submit Date: 10/31/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 305849

Location Name: PRONGHORN-65N61W Number: 8SWSW County: _____

Qtrqr: SWS Sec: 8 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.410330 Longitude: -104.240420

FACILITY - API Number: 05-123- -00 Facility ID: 305849

Facility Name: PRONGHORN-65N61W Number: 8SWSW

Qtrqr: SWS Sec: 8 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.410330 Longitude: -104.240420

CORRECTIVE ACTIONS:

1 CA# 200188

Corrective Action: Comply with Rule 1004. Recontour/grade and reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/13/2024

Operator Comment: Operator has reported that the location has been recontoured and areas of disturbance have been reseeded to comply with Rule 1004. Operator will continue to monitor and manage the location to stay in compliance with reclamation activities.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 11/29/2024 8:16:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404010759	Inspection Report Resolution
-----------	------------------------------

Total Attach: 1 Files