

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2024

Submitted Date:

11/26/2024

Document Number:

699700448**FIELD INSPECTION FORM**Loc ID 323895 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Frost, Joe	7137423642	jfrost@americanhelium.us	<a href="#">American Helium President</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211115	WELL	SI	06/01/2020	GW	045-06874	GOVT. 14-2	EI

**General Comment:**[ECMC Environmental Inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Lid is absent on the 37 bbl Produced Water plastic AST.			
Corrective Action:	Install or repair wildlife protection equipment.			Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

