

State of Colorado
Energy & Carbon Management Commission



Document Number:
404012712

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
12/03/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Distribution, Evergreen</u>	<u>719-846-7898</u>	<u>cogcc.evergreen@enrllc.com</u>
<u>D SANCHEZ, ZEKE</u>	<u>719-890-0376</u>	<u>zeke.sanchez@enrllc.com</u>
<u>-</u>		<u>dnr_ecmc_engineering@state.co.us</u>
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 716300065
Inspection Date: 09/30/2024 FIR Submit Date: 09/30/2024 FIR Status:

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308047

Location Name: KAHN-633S66W Number: 15NWSE County: LAS ANIMAS
Qtrqtr: NWSE Sec: 15 Twp: 33S Range: 66W Meridian: 6
Latitude: 37.170950 Longitude: -104.765960

FACILITY - API Number: 05-071-00 Facility ID: 260475

Facility Name: KAHN Number: 33-15
Qtrqtr: NWSE Sec: 15 Twp: 33S Range: 66W Meridian: 6
Latitude: 37.170950 Longitude: -104.765960

CORRECTIVE ACTIONS:

1 CA# 199181

Corrective Action: MAINTAIN WEEDS PER RULE 606. Date: 10/30/2024

Response: CA COMPLETED Date of Completion: 11/25/2024

Weeds cleared per rule 606

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 199182

Corrective Action: REMOVE UNUSED EQUIPMENT PER RULE 606.

Date: 10/30/2024

Response: CA COMPLETED

Date of Completion: 12/02/2024

Operator
Comment: Unused equipment removed per rule 606

ECMC Decision:

ECMC
Representative:

3 CA# 199183

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 10/30/2024

Response: CA COMPLETED

Date of Completion: 10/10/2024

Operator
Comment: MIT performed per rule 417

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed:

Title: Construction Technician

Date: 12/3/2024 6:50:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404012717	Unused equipment removed
404012722	Weeds cleared
404012723	Kahn MIT

Total Attach: 3 Files