

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2024

Submitted Date:

12/03/2024

Document Number:

715500947**FIELD INSPECTION FORM**Loc ID 313044 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 3975Name of Operator: ARGALI EXPLORATION COMPANYAddress: PO BOX 416City: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rector, Brian	(970) 629-1906	brector1983@gmail.com	
Rector, Jeff	(970) 629-2614	jbrduco@yahoo.com	
, Inspections		argaliexplorationcompany@gmail.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223438	WELL	PR	05/01/2023	GW	081-06804	STATE 1-31	PR

General Comment:**ECMC Inspection Report Summary**

On Monday, 12/02/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Argali Exploration Company on the State 1-31 well, Location #313044, in Moffat County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500835 on 10/16/24. The following Corrective Actions are unresolved and original due dates remain:

1. Relief vent riser caps missing.
2. Unused equipment.
3. Review of production records indicate operator is delinquent in submitting monthly operations reports.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(970) 629-1906	
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Methanol tank lacking containment. Empty and not in use.		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	11/01/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Unused Methanol tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:	Caps missing on relief vent risers		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.		Date: 10/27/2024

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500948	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6810091