

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 38-17 Pad
Location #: 335271



**Location Overview: Location is within High Priority/Density
Habitat areas & in close proximity NSO Habitat area.**

Section/Township/Range: 17 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 38-17 Pad
Location #: 335271



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.