


TEP Rocky Mountain LLC
Federal 399-1-5
Location ID: 316507



When replaced additional information will be required



Replace when illegible

**TEP Rocky Mountain LLC
Federal 399-1-5
Location ID: 316507**



Missing proper labeling



Faded and illegible

TEP Rocky Mountain LLC
Federal 399-1-5
Location ID: 316507



Unmarked anchor



Stained soil

TEP Rocky Mountain LLC
Federal 399-1-5
Location ID: 316507



Stained soil



Location from Northwest corner

**TEP Rocky Mountain LLC
Federal 399-1-5
Location ID: 316507**



Location from Northeast corner



Location from Southeast corner