

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2024

Submitted Date:

12/10/2024

Document Number:

715500975

FIELD INSPECTION FORM

Loc ID 316484 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279219	WELL	PR	01/01/2021	GW	103-10620	FEDERAL 399-2-1	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 12/10/2024, Inspector Kirby Burchett, conducted a routine field inspection at TEP Rocky Mountain LLC on the Federal 399-2-1 well, Location #316484, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Unlabeled tank

Refer to Inspection Photos for observed compliance issue.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol tank missing required labeling		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.	Date:	12/21/2024
Type	TANK LABELS/PLACARDS		
Comment:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-285-9377		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	Fence panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Fence panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Fence panels		
Corrective Action:			Date:

Equipment:

Type	#		corrective date
Ancillary equipment	# 1		
Comment:	Unlabeled methanol tank inside containment		
Corrective Action:			Date:
Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:		Unlined		
Corrective Action:				
		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:		Unlined		
Corrective Action:				
		Date:		

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 279219 Type: WELL API Number: 103-10620 Status: PR Insp. Status: PR

Producing Well

Comment: [September 2024 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Unlabeled tank
Drains						
Ditches						
		Ditches				
		Drains				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500976	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6819663