

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2024

Submitted Date:

12/11/2024

Document Number:

715800398

**FIELD INSPECTION FORM**

Loc ID 318276 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241019	WELL	SI	08/01/2024	OW	123-08807	CHARLES C BELL 2	SI

**General Comment:**

[This is a Wellsite Audit/Inspection.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Faded hard to read and needs to be replaced		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	01/11/2025

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241019 Type: WELL API Number: 123-08807 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Wednesday 12-11-2024 at approximately 1500 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection:                      Operator:KP Kauffman                      Location # 318276                      API #05-123-08807                      Well name: Charles C Bell 2                      County: Weld                      Weather:Cloudy, Clear                      Temp: 53*                      Location:Dry                      While there, I observed a wellsite, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      605.g Signs and Markers General Condition: CA date 1-11-2025                      See attached photos.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	12/11/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800400	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821377">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821377</a>