

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/12/2024

Document Number:

716800008

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Information:

Contact Name	Phone	Email	Comment
All Inspections		cogcc@kpk.com	
Brown, Kari		kari.oakman@state.co.us	
Watzman, Ross		rwatzman@kpk.com	

General Comment:

ECMC environmental inspection to determine progress on Spill ID 481679/Remediation 23488. Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Spill Discovery Date: 2/23/2022

Days since spill discovery: 1,015 days

Last report: 1/16/2023

Current site status:

Excavation remains open; no water was observed in the open excavation. Excavation is fenced with cattle fencing. Waddles placed around the open excavation have degraded, are ripping open, and have become trash. Small amount of unmarked soil stockpiled on location with no BMPs. Weeds present in the open excavation and throughout the location.

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716800009	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6823325