

State of Colorado
Energy & Carbon Management Commission



Document Number:

404028234

Date Received:

12/13/2024

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69805
Name of Operator: PETROX RESOURCES INC

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>COGCC</u>		<u>conor.pesicka@state.co.us</u>
<u>Nystrom, Dusty</u>	<u>(505)330-1328</u>	<u>nystrw@yahoo.com</u>
<u>Clark, Mike</u>	<u>(970)878-5594</u>	<u>mike.petrox@gmail.com</u>
<u>Clark, Ryan</u>	<u>(303)803-3998</u>	<u>ryan@petrox-resources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001431

Inspection Date: 11/01/2024

FIR Submit Date: 11/25/2024

FIR Status: _____

Inspected Operator Information:

Company Name: PETROX RESOURCES INC

Company Number: 69805

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

LOCATION - Location ID: 378718

Location Name: WRIGHT 33-5-N33N5W Number: 16SESW County: _____

Qtrqtr: SESW Sec: 16 Twp: 33N Range: 5W Meridian: N

Latitude: 37.099300 Longitude: -107.398690

FACILITY - API Number: 05-007-

-00

Facility ID: 378718

Facility Name: WRIGHT 33-5-N33N5W Number: 16SESW

Qtrqtr: SESW Sec: 16 Twp: 33N Range: 5W Meridian: N

Latitude: 37.099300 Longitude: -107.398690

CORRECTIVE ACTIONS:

1 CA# 200683

Corrective Action: Repair/perform maintenance at secondary containment devices per Rule 912.

Date: 11/25/2024

Response: CA COMPLETED

Date of Completion: 12/06/2024

Gravel was removed. See Attached pictures.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 200684

Corrective Action: Comply with rule 605. Post local emergency services number or 911 on well location signage.

Date: 11/25/2024

Response: CA COMPLETED

Date of Completion: 12/06/2024

Operator
Comment:

Please find attached photos

ECMC Decision:

ECMC
Representative:

3 CA# 200685

Corrective Action: Reclamation needs to be conducted in areas not needed for production operations in accordance with 1003 reclamation rules.

Date:

Response: CA COMPLETED

Date of Completion: 03/01/2021

Operator
Comment:

Petrox removed gravel, ripped, blanketed , installed stormwater, and re-seeded the areas not needed for the production phase of operations. Petrox plans to reseed the interim reclamation area this upcoming spring. Petrox emailed Corey McDonough asking what further measures we needed to take to ensure we meet the 1003 rule standards and is waiting to hear back on when we can have a site visit to discuss.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Clark

Signed:

Title: V.P. Engineering

Date: 12/13/2024 12:08:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404028277	Corrective Action Photos
-----------	--------------------------

Total Attach: 1 Files