

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/13/2024

Document Number:

713601698**FIELD INSPECTION FORM**Loc ID 484357 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10797Name of Operator: DESERT EAGLE OPERATING LLCAddress: 17330 PRESTON RD STE 200D-208City: DALLAS State: TX Zip: 75252**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ECMC Enforcement		dnr_ecmcenforcement@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	
Bulf, Cathy		cathybulf@gmail.com	
Butler, Brad	972-345-9195	butleroil@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484674	WELL	PR	11/28/2023	HE	071-09928	Red Rocks 1-14	RI

General Comment:

This is a reclamation inspection at the Red Rocks #1-14 wellsite.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	There is drilling activities occurring and no signage was posted.		
Corrective Action:	Install sign to comply with Rule 605.c.	Date:	12/18/2024
Type	WELLHEAD		
Comment:	No sign was installed at the location.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/13/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	There was an audible gas leak at the wellhead which was reported to an employee onsite.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	There were multiple fuel and oil containers not properly stored within secondary containment. There were multiple areas where equipment and/or containers had spilled fluid onto the surface. There was no liner and containment under the drilling equipment.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B. Comply with permit BMP/COA's.	Date:	12/13/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
	WELLHEAD			
Comment:	There was oil stained soils at the wellhead where the drilling rig was parked. The leak stained the soils approximately 40 ft. from the wellhead area.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B.	Date:	12/13/2024	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment [Soils on the location are not being protected from contamination, compaction, or erosion.](#)

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? Fail Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Interim reclamation is not progressing at the location or along the flowline disturbance area. There was recent drilling activities performed at the location and soils are now compacted. The flowline disturbance has not established vegetation but soils appear to have been reseeded. The are still vehicle tracks along the flowline which is creating unnecessary disturbance. The disturbed soils need to be stabilized until vegetation establishes with the use of BMP's such as (straw mulch, hydromulch, ect.) All soil decompaction, reclamation, and stabilization will need to be completed before the upcoming growing season.

Corrective Action Comply with 1003 Rules.

Date _____

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:						
Corrective Action:						Date
Overall Final Reclamation		Well Release on Active Location		Multi-Well Location		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		The perimeter stormwater controls are not maintained and are displaced. The wattles have been driven over and damaged.				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)C				Date: 12/16/2024
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601699	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6824371