

See Spaces for Additional Data on Reverse Side

37. SUMMARY OF POROUS ZONES:

SHOW ALL IMPORTANT ZONES OF POROSITY AND CONTENTS THEREOF; CORED INTERVALS; AND ALL DRILL-STEM TESTS, INCLUDING DEPTH INTERVAL TESTED, CUSHION USED, TIME TOOL OPEN, FLOWING AND SHUT-IN PRESSURES, AND RECOVERIES.

| FORMATION | TOP | BOTTOM | DESCRIPTION, CONTENTS, ETC. |
|-----------|------|-----------|----------------------------------|
| WEBER | 5580 | 6416 (TO) | OIL, GAS AND WATER BEARING SANDS |

38.

GEOLOGIC MARKERS

| NAME | TOP | |
|-----------|-------------|------------------|
| | MEAS. DEPTH | TRUE VERT. DEPTH |
| DAKOTA | 3103 | As M.D. |
| MORRISON | 3189 | " |
| CURTIS | 3816 | " |
| ENTRADA | 3927 | " |
| CARMEL | 4055 | " |
| NAVAJO | 4132 | " |
| CHINLE | 4718 | " |
| SHINARUMP | 4880 | " |
| MOENKOPI | 4935 | " |
| WEBER | 5580 | " |