

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404034048

Date Received:
12/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 600 17TH STREET STE 1400S
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Recipient, Single		Inspections@catamountep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708700072
Inspection Date: 12/11/2024 FIR Submit Date: 12/12/2024 FIR Status:

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC Company Number: 10464
Address: 600 17TH STREET STE 1400S
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325488

Location Name: PINE RIVER UNIT-M34N6W Number: 31SWSE County:
Qtrqtr: SWSE Sec: 31 Twp: 34N Range: 6W Meridian: M
Latitude: 37.142555 Longitude: -107.538946

FACILITY - API Number: 05-067- -00 Facility ID: 483038

Facility Name: Pine River 3-31 #1 Number:
Qtrqtr: SWSE Sec: 31 Twp: 34N Range: 6W Meridian: M
Latitude: 37.142555 Longitude: -107.538946

CORRECTIVE ACTIONS:

1 CA# 201004

Corrective Action: Repair hole in stormwater berm. Date: 01/08/2025

Response: CA COMPLETED Date of Completion: 12/12/2024

Operator Comment: Repaired hole in stormwater berm

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 12/18/2024 1:21:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404034048	FIR RESOLUTION SUBMITTED
404034057	Remedial Report

Total Attach: 2 Files