


Energy & Carbon Management Commission

RSU Anschutz Fed 4-62-2_1 SE 3 Location ID #454977 Issue Report






Created on December 18, 2024

Captured on December 18, 2024



Type	Count
Missing Capacity Label	3

No.	Type	Severity	Created	Status	Cost of Repair
1	 Missing Capacity Label	—	December 18, 2024	Open	—
2	 Missing Capacity Label	—	December 18, 2024	Open	—
4	 Missing Capacity Label	—	December 18, 2024	Open	—
					Total: \$0.00

Open

4 - Missing Capacity Label

Dec 18, 2024 at 8:58am



Details

Summary:

Missing Capacity Label

Created:

Dec 18, 2024, 3:24pm by Adam Burns

Cost of Repair:

—

Lat/Long:

40.33562, -104.30406

Open

2 - Missing Capacity Label

Dec 18, 2024 at 8:58am



Details

Summary:

Created:

Cost of Repair:

Lat/Long:

Missing Capacity Labels

Dec 18, 2024, 3:23pm by Adam Burns

—

40.33579, -104.30429

1 - Missing Capacity Label

Open

Dec 18, 2024 at 8:58am



Details

Summary:

Created:

Cost of Repair:

Lat/Long:

Missing Capacity Labels

Dec 18, 2024, 3:23pm by Adam Burns

—

40.33579, -104.30429