

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/19/2024

Document Number:

713400552**FIELD INSPECTION FORM**Loc ID 312617 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222045	WELL	PR	05/26/1993	GW	077-08647	HORSESHOE CANYON UNIT 2-21	PR

**General Comment:****CECMC Inspection Report Summary**

On 12/11/2024 at approximately 13:04 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Horseshoe Canyon/2-21 Pad at Location ID #312617 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Tanks and Berms - Open access to wildlife on tank/wildlife hazard/ available for entry by wildlife with a CA date of 12/26/2024
2. Equipment - Gas meter building roof paneling is damaged/wildlife hazard available for entry by wildlife with a CA date of 12/26/2024
3. Stormwater - Tunnel erosion NW side of lease road near location in ditch/ditch needs maintenance, also is a wildlife/personnel safety hazard with a CA date of 12/26/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location****Lease Road:**

Type	Access		
comment:	Access		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	1-800-891-6191/911	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Gas meter building roof paneling is damaged/wildlife hazard available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules	Date:	12/26/2024
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	1 unmarked deadman - All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:	Open access to wildlife on tank/wildlife hazard/ available for entry by wildlife, refer to photos				
	Tank not equipped with telemetry				
Corrective Action:	Comply with CECMC wildlife rules				Date: 12/26/2024

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		
Comment:				

Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	222045	Type:	WELL	API Number:	077-08647	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Fail			Tunnel erosion in ditch/ditch needs maintenance
Berms						
Compaction						
		Check Dams				
		Berms				
		Compaction				

Comment: Tunnel erosion NW side of lease road near location in ditch/ditch needs maintenance, also is a wildlife/personnel safety hazard, refer to photos

Corrective Action: Comply with CECMC Stormwater rules

Date: 12/26/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Tanks and Berms, Equipment and Stormwater for corrective actions & Equipment for comments.	popejoyd	12/19/2024
Limited storm water inspection due to snow cover		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400553	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834932">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834932</a>