

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2024

Submitted Date:

12/19/2024

Document Number:

713601714

FIELD INSPECTION FORM

Loc ID 380903 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10791

Name of Operator: WAVETECH HELIUM INC

Address: 1801 BROADWAY SUITE 600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
JOBE PATRICK		pjobe@wavetechenergy.com	
GENDELMAN IGOR		igendelman@wavetechenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208189	WELL	PR	10/20/2023	GW	017-07124	UPRC 1 Eiger 14-11	RI

General Comment:

This is a reclamation inspection at the UPRC 1 Eiger #14-11 wellsite.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	There was weed debris along the tank berm and near equipmet that needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	12/31/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	
Comment:	There are stained soils at the wellhead and there was a spill that occurred at the tank which stained the soils and liner. The source of the leak must be repaired and controlled stained material cleaned up.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 01/17/2025

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		200 BBLS			39.017910,-102.200410
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficent		Inadequate
Comment:	The berm around the tank is worn down and contains loose soils which is not designed to resist degradation from erosion. Operator must construct secondary containment per Rule 603.o.			

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date:	01/17/2025
--------------------	--	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

There is a pile of topsoil at the east and west side of the location which are not protected from degradation and weed infestation. There are signs of erosion and weeds along the topsoil pile.

Corrective Action _____

Comply with 1002.c

Date **01/17/2025**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? Fail
1003c. Compacted areas have been cross ripped? Fail
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? Fail Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATIONCropland

Top soil replaced Fail Recontoured Fail Perennial forage re-established Fail

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment

Interim reclamation was not conducted within 3 months of drilling or subsequent operations. There are undesirable weeds throughout the location that were not controlled. All disturbed areas including the access road must be reduced in size and reclaimed. Disturbed soils will need to be decompacted by criss ripping to at least 18 inches. The topsoil piles will need to be replaced and recontoured.

Corrective Action

Comply with the 1003 interim reclamation rules.

Date 01/17/2025Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action:		Date	
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601715	inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834933