

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2024

Submitted Date:

12/19/2024

Document Number:

713601716**FIELD INSPECTION FORM**Loc ID 485761 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10791Name of Operator: WAVETECH HELIUM INCAddress: 1801 BROADWAY SUITE 600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jobe, Patrick	(303) 534-3383	pjobe@wavetechenergy.com	
GENDELMAN IGOR		igendelman@wavetechenergy.com	

**General Comment:**

This is a contruction inspection at the UPRC 1 Eiger #14-11 wellsite.  
See attached photos and additional details within this report.

**Location Construction**

Location ID: 486184 CDP: \_\_\_\_\_

Comment: It was observed that construction had began at this location and there was no form 42 notice provided for the start of construction. Operator will need to withhold further construction activities until a form 42 construction notice is submitted. A form 42 notice must be provided 2 business days in advance of commencing construction.

Corrective Action: Comply with Rule 405.b.

Date: 12/19/2024

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:\_\_\_\_\_  
\_\_\_\_\_Summary of Operator Response to Landowner Issues:\_\_\_\_\_  
\_\_\_\_\_Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:\_\_\_\_\_  
\_\_\_\_\_**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601717	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834934">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834934</a>