

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2024

Submitted Date:

12/24/2024

Document Number:

718600086

FIELD INSPECTION FORM

 Loc ID 464916 Inspector Name: Dunnam, Anthony On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 ECMC Operator Number: 4680
 Name of Operator: DCP OPERATING COMPANY LP
 Address: 2331 CITYWEST BLVD., S812-02
 City: HOUSTON State: TX Zip: 77042
Contact Information:

Contact Name	Phone	Email	Comment
Weathers, Steve		SWWeathers@dcpmidstream.com	
Hayes, Brandon	970-378-6389	bshayes@dcpmidstream.com	Environmental Specialist
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452046	SPILL OR RELEASE	CL	01/30/2018		-	Doris 1/ Dottie 12-34 Tank Leak	RI
484701	SPILL OR RELEASE	CL	09/01/2023		-	CR55/CR4 (AT-1-1-1-6-3) 5/2023	RI

General Comment:

This is an inspection of groundwater monitoring wells associated with remediation project #31076.

While conducting an inspection on location ID #464916 new bore holes and groundwater monitoring wells were documented.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:	#		corrective date
Comment:	Operator appears to be in process of installing new groundwater monitoring wells. The locations approximately match operator provided site map (Photo 5) see attached.		
	Unlabeled barrels stored on site near separator may be associated with groundwater monitoring project. All waste and debris should be removed and disposed of in accordance with 900 series rules.		
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 452046 Type: SPILL OR API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484701 Type: SPILL OR API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation project #31076 based on spill #484701 remains open.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718600087	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6852403