

Inspection Photos
Location Name: Franson 42-33 4N47W
API Number: 125-12121



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos

Location Name: Franson 42-33 4N47W

API Number: 125-12121



3. Well location overview.



4. Lease sign at remote gathering location.

Inspection Photos
Location Name: Franson 42-33 4N47W
API Number: 125-12121



5. Gas meter inside meter shed.



6. Remote gathering location overview.