

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2024

Submitted Date:

12/24/2024

Document Number:

718600107

FIELD INSPECTION FORM

Loc ID 319319 Inspector Name: Dunnam, Anthony On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 10 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross		rwatzman@kpk.com	
,		dnr_cogccenforcement@state.co.us	COGCC Enforcement
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
McCoy, Diane		diane.mccoy@state.co.us	
Jenkins, Steve		steve.jenkins@state.co.us	
,		cogcc@kpk.com	ALL INSPECTIONS
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243270	WELL	SI	04/01/2024	GW	123-11061	BBR ABBOTT FARMS 22-34	RI
319319	LOCATION	AC			-	BBR ABBOTT FARMS-61N64W 34SEW	RI

General Comment:

This is a Final Reclamation and Stormwater Inspection on well (Location ID: 319319, API:123-11061). The Form 6s remains in process. It appears the well was plugged on 09/16/2022.

The tank battery associated with this well has a separate location ID (#464350) and will be inspected under FIR #718600111.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Undesirable weeds are present at the location (Kochia, Russian thistle).

Corrective Action: Comply with Rule 606.c. Control weeds on location.

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment: Open excavation fencing is not adequately installed to prevent entry.

Comply with Rule 913.b.5.B. Repair fencing around open excavations. See environmental section for corrective actions.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 243270 Type: WELL API Number: 123-11061 Status: SI Insp. Status: RI

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 319319 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation project #24284 remains open and operator has failed to provide quarterly updates. Soil samples associated with well closure and flowline removal have not been submitted. Open excavation remains at well location. Due to the presence of a liner there may be contaminated soils without appropriate stormwater BMPs. Fencing is not adequate to prevent entry.

Corrective Action: **Comply with Rules 911 and 913.**

Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled **Fail**

Debris removed **Fail** No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage **Fail**

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Perform reclamation in accordance to Rule 1004.						Date: _____
Overall Final Reclamation		Fail	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Excavated soil pile does not have appropriate BMPs installed to prevent erosion (perimeter erosion controls and material covering). See attached photos.						Date: _____
Corrective Action: Install stormwater BMPs according to Rule 1002.f.2.						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>The flowline section of this report may not be visible in an email preview. The flowline section reads as follows;</p> <p>Comment: Flowline does not appear to have been removed. Flowline abandonment verification Form 44 has not been submitted. According to operator submitted document #403203597 landowner requested flowline removal. See attached pictures</p> <p>Corrective Action: Remove flowline according to Rule 1105 and submit Form 44 flowline abandonment verification.</p>	dunnama	12/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404040047	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6852272
718600107	INSPECTION APPROVED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857866
718600124	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6852270