

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2024

Submitted Date:

01/02/2025

Document Number:

713400578**FIELD INSPECTION FORM**Loc ID 334103 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**35 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273408	WELL	PR	09/01/2017	GW	045-10246	HYRUP 2-68	SI
290196	WELL	PR	06/01/2014	GW	045-14035	HYRUP 2-34C (2O)	PR
290245	WELL	SI	05/01/2024	GW	045-14056	HYRUP 2-44B	SI
290246	WELL	PR	01/01/2011	GW	045-14067	HYRUP 2-34B (2O)	SI
290247	WELL	PR	08/01/2024	GW	045-14066	HYRUP 2-34A	PR
290252	WELL	PR	04/01/2022	GW	045-14061	HYRUP 11-41B (2O)	PR
290253	WELL	SI	02/01/2022	GW	045-14060	HYRUP 11-41A	SI
290254	WELL	PR	09/01/2017	GW	045-14059	HYRUP 11-31A (2O)	PR
290255	WELL	SI	06/01/2024	GW	045-14058	HYRUP 2-44D	SI
290256	WELL	PR	04/30/2010	GW	045-14057	HYRUP 2-44C	SI
290258	WELL	PR	06/29/2010	GW	045-14055	HYRUP 2-44A	SI

General Comment:

CECMC Inspection Report Summary

On 12/30/2024 at approximately 15:10 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at QB ENERGY HYRUP/2-34B (PAD - 2 0) at Location ID #334103 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Stormwater - Improperly stored chemicals next to wellheads with a CA date of 01/5/2025
2. Equipment - Multiple open holes in separator buildings open to wildlife/ available for entry by wildlife with a CA date of 01/9/2025

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Inaccurate operator contact number on all production tank labels		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-(866)-580-9382/911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Automation - Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Other	# 4		
Comment:	Multiple open holes in separator buildings open to wildlife/ available for entry by wildlife, refer to photos		
Corrective Action:	Comply with CECMC wildlife rules	Date:	01/09/2025
Type: Plunger Lift	# 11		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:	No form of pressure monitoring equipment. Bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	Tanks equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Separate centralized containment			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment: 2 tanks equipped with telemetry						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Separate centralized containment				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 273408 Type: WELL API Number: 045-10246 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in at separator

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290196 Type: WELL API Number: 045-14035 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290245 Type: WELL API Number: 045-14056 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last produced April 2024

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290246 Type: WELL API Number: 045-14067 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut in at separator

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290247 Type: WELL API Number: 045-14066 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290252 Type: WELL API Number: 045-14061 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290253 Type: WELL API Number: 045-14060 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced January 2022

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290254 Type: WELL API Number: 045-14059 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on plunger lift

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290255 Type: WELL API Number: 045-14058 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced May 2024

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290256 Type: WELL API Number: 045-14057 Status: PR Insp. Status: SI**Producing Well**

Comment: _____

Corrective Action: _____

Date: _____

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in at separator

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290258 Type: WELL API Number: 045-14055 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut in at separator

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction
		Ditches				
		Gravel				Sparse
				Material Handling And Spill Prevention	Fail	Improperly stored chemicals
Ditches						
Berms						
Gravel						Sparse
		Culverts				
Compaction						Light compaction
Tracking Pad						

Comment: [Improperly stored chemicals next to wellheads](#)Corrective Action: [Comply with CECMC Storm water rules](#)

Date: 01/05/2025

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Stormwater & Equipment for corrective actions and Signs/Marker for comments.	popejoyd	01/02/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400579	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6861561