

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2024

Submitted Date:

12/30/2024

Document Number:

717000218**FIELD INSPECTION FORM**Loc ID 319981 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		conor.pesicka@state.co.us	
,		randy.silver@state.co.us	
,		cogcc@kpk.com	All Inspections
Supervisor, ECME		jason.gomez@state.co.us	

General Comment:[Follow-up inspection](#)

Location

Lease Road:			
Type	Access		
comment:	No access, lease road access gate locked and no key		
Corrective Action	Rule 204 ACCESS. Location is not accessible during normal business hours. Provide key, combinations, or alternate method of access to comply with rule 204. Corrective Action Date 1/7/2024. See attached photo	Date:	01/07/2025

Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary</p> <p>On Thursday December 19th, 2024 at approximately 11:12am. I, Inspector Chane Finkenbinder, conducted a Follow up inspection.</p> <p>This is a follow up inspection of DOC# 717000074– It appears that no actions were taken to correct the corrective actions from DOC# 717000074</p> <p>Operator: KP KAUFFMAN COMPANY INC</p> <p>Location name: UPRR 23 PAN AM UT D#4</p> <p>API # 05-001-07497</p> <p>Location ID #: 319981</p> <p>County: Adams</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Rule 204 ACCESS. Location is not accessible during normal business hours. Provide key, combinations, or alternate method of access to comply with rule 204. Corrective Action Date 1/7/2025. See attached photo # 1.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	12/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404043400	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857305
717000219	Inspection photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6857281