

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2025

Submitted Date:

01/06/2025

Document Number:

715800492**FIELD INSPECTION FORM**Loc ID 318405 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241237	WELL	PR	07/01/2024	OW	123-09025	DITLEV-SIMONSEN C 3	PR

General Comment:[This is a wellsite audit/inspection.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate, starting to fade and will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Dead vegetation around the wellsite needs to be addressed.		
Corrective Action:	Comply with Rule 606.	Date:	01/13/2025

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box and transformers		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	241237	Type:	WELL	API Number:	123-09025	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:		02/02/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:		Plumbed to surface							
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 1-6-2025 at approximately 1425 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection:</p> <p>Operator: KP Kauffman</p> <p>Location #318405</p> <p>API #05-123-09025</p> <p>Well name:Ditlev-Simonsen C3</p> <p>County: Weld</p> <p>Weather: Cloudy & cold</p> <p>Temp: 38*</p> <p>Location: Dry</p> <p>While there, I observed wellsite, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>606 Houskeeping: CA date 1-13-2025</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	01/06/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800493	Location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6865641