

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2025

Submitted Date:

01/09/2025

Document Number:

711901673

FIELD INSPECTION FORM

Loc ID: 313655 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224745	WELL	SI	08/01/2022	OW	087-05130	PETERSON, MAX 1	SI

General Comment:

WO RIG ON LOCATION - P&A IN PROCESS DAY (3)

Inspected Facilities

Facility ID: 224745 Type: WELL API Number: 087-05130 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: BOHLER WELL

Contractor Phone: 970-580-2653

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 5110, 4000

Cement Volume (sx): 4+30

Good Return During Job: _____

Cement Type: _____

Comment: SAFETY MEETING- WARM UP RIG - RUWL- SET CIBP @ (5110') W/4 SXS ON TOP - SET CIRC @ (4000') PERF AND SQUEEZE (60) SXS THROUGH CIRC @ (3950') W/(4) SKS ON TOP - - - COULD NOT DRIVE CEMENT THROUGH PERFS AT (4000'), PRESSURED UP TO (1500 PSI), PRESSURE HELD (NO LOSS), DETERMINED THE BACKSIDE CEMENTING THROUGH PERFS WAS NOT EFFECTIVE - DECIDED TO STING OUT OF CIRC PLACE (30) SKS AND PREPARE TO SET NEXT PLUG @ (1500') THE FOLLOWING DAY.
INSPECTOR SCHURE ELECTED TO CHANGE PLUGGING ORDERS RELATED TO THE (4000') PLUG IN THE FIELD, CONSULTING WITH STEVE WOLFE P.E. SHUT DOWN FOR NIGHT (EXTREME COLD CONDITIONS)

Corrective Action: _____

Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: P&A IN PROCESS

Corrective Action: _____

Date: _____

Workover

Comment: RIG ON LOCATION

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
P&A IN PROGRESS DAY (3)	schureky	01/09/2025