

KT Resources LLC
Federal B-25-2-97
Location ID: 315965



Stained soils



Stained soils

KT Resources LLC
Federal B-25-2-97
Location ID: 315965



Lack of Stormwater BMP maintenance



Lack of Stormwater BMP maintenance

**KT Resources LLC
Federal B-25-2-97
Location ID: 315965**



Lack of Stormwater BMP maintenance



Lack of Stormwater BMP maintenance



KT Resources LLC
Federal B-25-2-97
Location ID: 315965



Lack of Stormwater BMP maintenance

EMPACT ANALYTICAL SYSTEMS INC.
365 SOUTH MAIN
BRIGHTON, CO 80601
303-637-0150 www.empactanalytical.com

Meter S/N
15827587
000-54313

Station Name Federal B-25-2-97
Station No. B-25 Producer 31 Op.
Sec 31 Township 2N Range 97W
Diff 250" Temp Range 0-150" Tube Size 2.069
Static 200# Absolute 11.89 psig

	Date	Orifice Plate Size	Meter Test Date	Sample Date
GM	3-7-18	1.625	3-7-18	3-7-18
KB	2-27-19	0.625	2-27-19	3-19-19
CW. 8198	9-10-19	0.875	9-10-19	9-10-19
	2-8-22	0.875	2-8-22	

Calibration overdue

**KT Resources LLC
Federal B-25-2-97
Location ID: 315965**



Tank battery signs



Entrance sign replacement will require additional information



KT Resources LLC
Federal B-25-2-97
Location ID: 315965



Well sign replacement will required additional information



Debris

KT Resources LLC
Federal B-25-2-97
Location ID: 315965



Debris



Debris

KT Resources LLC
Federal B-25-2-97
Location ID: 315965



Oily waste and stained soil



Oily waste and stained soil

**KT Resources LLC
Federal B-25-2-97
Location ID: 315965**



Debris



Oily waste and stained soil

**KT Resources LLC
Federal B-25-2-97
Location ID: 315965**



Location from Northwest corner



Location from Southwest corner

**KT Resources LLC
Federal B-25-2-97
Location ID: 315965**



Location from Southeast corner



Location from Northeast corner