

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404055690

Date Received:
01/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
4 of 4 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
General sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001584
Inspection Date: 12/11/2024 FIR Submit Date: 12/13/2024 FIR Status:

Inspected Operator Information:

Company Name: SIMCOE LLC Company Number: 10749
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 334175

Location Name: DOLLAHON 18U-1-M34N7W Number: 18NWNE County:
Qtrqtr: NWNE Sec: 18 Twp: 34N Range: 7W Meridian: M
Latitude: 37.195944 Longitude: -107.649529

FACILITY - API Number: 05-067- -00 Facility ID: 334175

Facility Name: DOLLAHON 18U-1-M34N7W Number: 18NWNE
Qtrqtr: NWNE Sec: 18 Twp: 34N Range: 7W Meridian: M
Latitude: 37.195944 Longitude: -107.649529

CORRECTIVE ACTIONS:

1 CA# 201027

Corrective Action: control and contain spills and clean up per rule 912.a. Date: 12/20/2024

Response: CA COMPLETED Date of Completion: 01/10/2025

Operator Comment: Chemicals removed.

ECMC Decision:

ECMC
Representative:

2 CA# 201028

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 01/12/2025

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Landowner equipment removed.

ECMC Decision: _____

ECMC
Representative:

3 CA# 201029

Corrective Action: Comply with rule 606. remove debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Landowner debris removed.

ECMC Decision: _____

ECMC
Representative:

4 CA# 201030

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.

Date: 12/20/2024

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Stormwater BMPs installed at gully erosion.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions completed. See attachment for photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: permitting specialist I

Date: 1/13/2025 11:33:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404055700	Completion photos for Dollahon 18U-01 2,4

Total Attach: 1 Files