

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404055690

Date Received:

01/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001584

Inspection Date: 12/11/2024

FIR Submit Date: 12/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 334175

Location Name: DOLLAHON 18U-1-M34N7W Number: 18NWNE County: _____

Qtrqtr: NWNE Sec: 18 Twp: 34N Range: 7W Meridian: M

Latitude: 37.195944 Longitude: -107.649529

FACILITY - API Number: 05-067- -00 Facility ID: 334175

Facility Name: DOLLAHON 18U-1-M34N7W Number: 18NWNE

Qtrqtr: NWNE Sec: 18 Twp: 34N Range: 7W Meridian: M

Latitude: 37.195944 Longitude: -107.649529

CORRECTIVE ACTIONS:

1 CA# 201027

Corrective Action: control and contain spills and clean up per rule 912.a.

Date: 12/20/2024

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Chemicals removed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 201028

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 01/12/2025

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Landowner equipment removed.

ECMC Decision:

ECMC
Representative:

3 CA# 201029

Corrective Action: Comply with rule 606. remove debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Landowner debris removed.

ECMC Decision:

ECMC
Representative:

4 CA# 201030

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.

Date: 12/20/2024

Response: CA COMPLETED

Date of Completion: 01/10/2025

Operator
Comment: Stormwater BMPs installed at gully erosion.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions completed. See attachment for photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: permitting specialist I

Date: 1/13/2025 11:33:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404055690	FIR RESOLUTION SUBMITTED
-----------	--------------------------

404055700	Completion photos for Dollahon 18U-01 2,4
-----------	---

Total Attach: 2 Files