

Weld OEM Spill Report Form

Submitted on	4 January 2025, 1:55PM
Receipt number	3000
Related form version	19

Company

Company name	Verdad Resources
Address	1125 17th Street, Suite 600
City	Denver
State	Colorado
Zip code	80202

Contact Information

Contact person	Dean Wagoner
Contact phone	720-647-6852
Contact email	dwagoner@verdadresources.com

About the Spill

Date incident occurred	01/04/2025
How long did the spill/ release occur	approximately 1-8 hours
Was 9-1-1 called for this incident	No
Longitude	-104.703514
Latitude	40.001755
Fire department/district	Hudson Fire
Where did the incident occur?	Oil and gas facility/pipeline

Oil and Gas Incident

Well site name	County Line
Section	31
Township	1N
Range	65W
Where did the spill occur	Pipeline
Have you submitted a form 19	Yes
Form 19 report number	404047859

Product Spilled

Product spilled	Oil and Produced Water
Number of barrels spilled	1
Emergency precautions taken	N/A
Extremely hazardous substance	No
Acute or chronic health risks	No
Did the spill affect or end near a waterway, irrigation ditch, or a retention pond?	No
What caused the spill/release?	Weld or joint failure

Narrative

Include specific incident information and mitigation actions taken to stop and clean-up the spill/release

Flowline between east well header rack and bulk separator leaking under surface. 24 hour pad supervision shut in corresponding wells and isolated the correct flow line. The active leak immediately stopped. Hydrovac was dispatched all free liquids were recovered and some contaminated soil. Investigation and cleanup under way.

Acknowledgement

I acknowledge that a written follow-up notice must be submitted to Weld County OEM/LEPC as soon as practicable after the release. The follow-up notice must update information included in the initial notice and provide information on actual response actions taken and advice regarding medical attention necessary for citizens exposed.