

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2025

Submitted Date:

01/15/2025

Document Number:

711901756

**FIELD INSPECTION FORM**

Loc ID 313689 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10657  
Name of Operator: PCR OPERATING LLC  
Address: 9211 BROADWAY ST #17493  
City: SAN ANTONIO State: TX Zip: 78217

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beasley, Nolan		nolan.beasley@state.co.us	
,		sperson@passcreekresources.com	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224865	WELL	SI	10/01/2022	OW	087-05257	SCRITSMIER, A B 5	SI

**General Comment:**

**UIC 2025 REPORT - OPERATOR OF RECORD: PCR OPERATING LLC – ADENA FIELD – MORGAN COUNTY COLORADO. FIELD INSPECTIONS HAVE CONCLUDED THAT THE ADENA FIELD HAS BEEN ABANDONED BY OPERATOR OF RECORD – UTILITIES (ELEC. POWER) HAS BEEN DISCONNECTED BY SERVICE PROVIDER (XCEL ENERGY) ALL WELLS ARE NON-OPERATIONAL AT TIME OF THIS REPORT. NO PCR STAFF AVAILABLE FOR GAUGING WELLS TO TEST PRESSURES – THIS UIC FIR WILL REPRESENT WELL PRESSURES AS (0) ZERO BASED ON LAST PHYSICAL PRESSURE GAUGE REPORTING. ADENA FIELD ANTICIPATED TO ENTER THE OWP FOR PLUGGING OF WELLS AS OF THE DATE OF THIS REPORT. ECMC ENGINEERING/ENFORCEMENT GROUPS WILL UPDATE DISPOSITION/CONCLUSIONS OF ADENA FIELD STATUS IN 2025.**

**Inspected Facilities**

Facility ID: 224865 Type: WELL API Number: 087-05257 Status: SI Insp. Status: SI

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND  
 TC: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ Last MIT: 06/08/2018  
 Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: NO PRESSURE ON WELL

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
UIC 2025 REPORT - OPERATOR OF RECORD: PCR OPERATING LLC – ADENA FIELD – MORGAN COUNTY COLORADO. FIELD INSPECTIONS HAVE CONCLUDED THAT THE ADENA FIELD HAS BEEN ABANDONED BY OPERATOR OF RECORD – UTILITIES (ELEC. POWER) HAS BEEN DISCONNECTED BY SERVICE PROVIDER (XCEL ENERGY) ALL WELLS ARE NON-OPERATIONAL AT TIME OF THIS REPORT. NO PCR STAFF AVAILABLE FOR GAUGING WELLS TO TEST PRESSURES – THIS UIC FIR WILL REPRESENT WELL PRESSURES AS (0) ZERO BASED ON LAST PHYSICAL PRESSURE GAUGE REPORTING. ADENA FIELD ANTICIPATED TO ENTER THE OWP FOR PLUGGING OF WELLS AS OF THE DATE OF THIS REPORT. ECMC ENGINEERING/ENFORCEMENT GROUPS WILL UPDATE DISPOSITION/CONCLUSIONS OF ADENA FIELD STATUS IN 2025.	schureky	01/15/2025