



# LORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT



☐ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

☒ NOTICE OF SATISFACTORY INSPECTION

SCANNED

API No. 05- 087 - 8095

LEASE NAME: Danford #1

LOCATION: SENW 9-2N-58W

OPERATOR: Western Operating

DATE: 10-20-97

INSPECTOR: EBB

Insp. Type: SR

Insp. Status: DA

PA: Y N

Pass/Fail: P F

Viol.: Y N

NOV: Y N

## INSPECTION ITEM

## COMMENTS

## INPUT

### Well ID Signs

(Rule 210, 604.c(4))

### Pits (Reserve/Production)

(Rule 902, 903, 904, 905)

### Fences

(Rule 603.b.7, 604.C.(3), 1002.A)

### Tank Battery Equipment

(Rule 603.b.3, 604)

### Fire Walls/Berms/Dikes

(Rule 603.b.12, 604)

### General Housekeeping

(Rule 603)

### Spills (Oil/Water)

(Rule 907)

### Bradenhead

(Rule 207.b)

### Drilling Well/Workover

(Rule 317)

### Surface Rehabilitation

(Rule 1002, 1003, 1004, 1103)

### Miscellaneous

grass growing on site in  
range land! mud spread  
offsite noted.

CORRECTIVE ACTION REQUIRED: Written permission required to  
spread mud off-site.

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

NOV - 6 1997