



00080113

COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>087 - 08895</u>		LEASE NAME: <u>Danford - 1</u>	
LOCATION: <u>SENW 9-2N-58W</u>		OPERATOR: <u>Western (on-site)</u>	
DATE: <u>5-29-96</u>		INSPECTOR: EBB \ Ed Binkley (970) 842-4465	
Insp. Type: <u>DE</u>	Insp. Status: <u>DE</u>	PA: Y <input type="checkbox"/> N <input type="checkbox"/>	Pass/Fail: <u>PS</u> F <input type="checkbox"/> Viol.: Y <input checked="" type="checkbox"/> N <input type="checkbox"/> NOV: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>

INSPECTION ITEM (RULE)	COMMENTS	INPUT
Well ID Signs (210)	<u>Ag</u>	
Pits (Reserve/Production)(904)		
Fences (604 C.(3), 1003 A.)		
Tank Battery Equipment(604)		
Fire Walls/Berms/Dikes(604)		
General Housekeeping (603g)		
Spills(Oil/Water)(907)		
Bradenhead (207)		
Drilling /Workover (315)	<u>MIALL Ashby Drilling</u>	
Surface Rehabilitation (317)		
Miscellaneous	<u>Location constructed 5-28-96</u>	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission. Submit a copy or FAX to the inspector with date remedied and your signature. EBB fax is 970-842-4467.

White - File Green - Operator Canary - Well Site