

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/15/2025

Document Number:

714202024

FIELD INSPECTION FORMLoc ID 332862 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross		rwatzman@kpk.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections
Norton, Matthew		mnorton@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240882	WELL	SI	07/01/2024	GW	123-08670	MUSICK-MCCLINTOCK 1	SI

General Comment:

This is an audit of MUSICK-McCLINTOCK #1 scout card and related documents followed by a field inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	No contents or capacity displayed on one tank, no signage displayed at another tank. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 04/19/2024
Type	BATTERY		
Comment:	Adequate (faded)		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate (faded)		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil inside berm. See attached photo.		
Corrective Action:	Comply with 609. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.		Date: 04/19/2024
Type	WEEDS		
Comment:	overgrown dead vegetation on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 04/19/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	wire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities										
Facility ID:	240882	Type:	WELL	API Number:	123-08670	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT ONSITE				
Comment:		SI; valves appear to be in the closed position.								
Corrective Action:								Date:		
BradenHead										
Date of Last Brhd Test:		04/25/2024		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		20		Fluid Type:				
		End Surf Csg Pressure:		0						
Comment:										
Corrective Action:								Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714201813. All previous corrective actions assigned to this location have not been resolved. All previous corrective actions have been re-assigned with their original corrective action dates. No new corrective actions were observed at the time of re-inspection. Please review my findings below.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, some snow in various areas (approx. 1"-3" of snow) On Wednesday, January 15, 2025 at approximately 1045, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-McCLINTOCK #1 (KP Kauffman Company, Inc), at location ID: 332862 in WELD COUNTY, Colorado. While there, I observed a shut-in facility. During this inspection the following possible compliance issues were observed: 1. It appears to be no capacity or contents displayed on one tank and no signage displayed at another tank. Install sign to comply with Rule 605.h. (Corrective Action Date: April 19, 2024) See attached photo #2, 11. 2. It appears to be stained soil inside earthen berm. Comply with Rule 609.e. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d. (Corrective Action Date: April 19, 2024) See attached photo #6. 3. It appears to be dead, overgrown vegetation on multiple areas of location. Comply with Rule 606. (Corrective Action Date: April 19, 2024) See attached photo #3-5, 7-10, 12.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	01/15/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404059878	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6877759
714202025	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6877749