



COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

SCANNED

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <i>087 - 5588</i>		LEASE NAME: <i>Marguart 1</i>	
LOCATION: <i>SWSE 29-2N-57</i>		OPERATOR: <i>Mona han</i>	
DATE: <i>2-13-96</i>		INSPECTOR: <i>Binkley</i>	
Insp. Type: <i>PR</i>	Insp. Status: <i>51</i>	PA: Y N	Pass/Fail: P <input checked="" type="radio"/> F Viol.: Y <input checked="" type="radio"/> N NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	<i>Need well signs</i>	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)	 00086109	
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	<i>submersible pump dropped into hole.</i>	

CORRECTIVE ACTION REQUIRED: <i>Install well head signs per Rule 210-B Submit Form 4, status.</i>	
Date Corrective Action Required By: <i>4-30-96</i>	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.