

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2025

Submitted Date:

01/17/2025

Document Number:

713601792

**FIELD INSPECTION FORM**Loc ID 324789 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324789	LOCATION	AC			-	WEAR-619S45W 5NWSE	RI

**General Comment:**

This is a follow up of the previous inspection at the Wear #1 location..

See attached photos and additional details within this report.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign is present.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	OTHER	
Comment:	The storage building has been repaired with new tin installed along the side. Previous CA has been completed.	
Corrective Action:		Date:
Type	STORAGE OF SUPL	
Comment:	The center storage area was cleaned out and organized. The north portion of the shed still remains with scattered supplies. Additional cleanup is required to complete this corrective action.	
Corrective Action:	Comply with Rule 606 for Good Housekeeping and Rule 610 Fire Prevention and Protection.	Date: 01/10/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the access road that has become rutted and eroded. This area will require BMP's such as gravel for stabilization. Install or repair required BMPs per Rule 1002.f.(2)C

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404061960	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880162">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880162</a>
713601793	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880125">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6880125</a>