

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404086665

Date Received:  
02/11/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:  
5 of 5 CAs from the FIR responded to on this Form  
5 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name	Phone	Email
<u>Reid, Marta</u>		<u>marta@westernoperating.com</u>
<u>JAMES STEVEN D</u>		<u>steve@westernoperating.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 690202223  
Inspection Date: 10/27/2021 FIR Submit Date: 10/28/2021 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: WESTERN OPERATING COMPANY Company Number: 95620  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204

**LOCATION** - Location ID: 324797

Location Name: DAWSON A-619S45W Number: 9NENW County: KIOWA  
Qtrqtr: NENW Sec: 9 Twp: 19S Range: 45W Meridian: 6  
Latitude: 38.424060 Longitude: -102.466500

**FACILITY** - API Number: 05-061-00 Facility ID: 212663

Facility Name: DAWSON A Number: 1  
Qtrqtr: NENW Sec: 9 Twp: 19S Range: 45W Meridian: 6  
Latitude: 38.424060 Longitude: -102.466500

**CORRECTIVE ACTIONS:**

**1** CA# 157241

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1). Date: 11/12/2021

Response: CA COMPLETED Date of Completion: 01/30/2022

Operator Comment: Steel Panel has been replaced and a linear was installed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 157243

Corrective Action: Properly dispose of oily waste in accordance with 905.e.

Date: 11/12/2021

Response: CA COMPLETED

Date of Completion: 08/12/2023

Operator  
Comment:

Oil stained soils within secondary containment were properly cleaned up and disposed of.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 157244

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 11/12/2021

Response: CA COMPLETED

Date of Completion: 02/01/2022

Operator  
Comment:

Fencing is in place to prevent Livestock entry.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 157245

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 12/01/2021

Response: CA COMPLETED

Date of Completion: 03/01/2022

Operator  
Comment:

Interim reclamation at the south side of the tank has been completed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 157423

Corrective Action: Contact COGCC EPS staff regarding Rule 912.c.  
Clean up and remove stained soils per Rule 912.a.  
Properly dispose of oily waste in accordance with 905.e.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 01/21/2022

Operator  
Comment:

Location is under Remedial Project #21723

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 2/11/2025 4:09:39 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404089772	Location Photos
-----------	-----------------

Total Attach: 1 Files