

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404089782

Date Received:

02/11/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

JAMES STEVEN D

steve@westernoperating.com

Kosola, Jason

jason.kosola@state.co.us

Reid, Marta

marta@westernoperating.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 690202486

Inspection Date: 01/12/2022

FIR Submit Date: 01/14/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: WESTERN OPERATING COMPANY

Company Number: 95620

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

### LOCATION - Location ID: 324797

Location Name: DAWSON A-619S45W

Number: 9NENW

County: KIOWA

Qtrqtr: NENW

Sec: 9

Twp: 19S

Range: 45W

Meridian: 6

Latitude: 38.424060

Longitude: -102.466500

### FACILITY - API Number: 05-061-

-00

Facility ID: 212663

Facility Name: DAWSON A

Number: 1

Qtrqtr: NENW

Sec: 9

Twp: 19S

Range: 45W

Meridian: 6

Latitude: 38.424060

Longitude: -102.466500

### CORRECTIVE ACTIONS:

1 CA# 159215

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 11/12/2021

Response: CA COMPLETED

Date of Completion: 01/30/2022

Operator Comment: Steel Panel has been replace and a linear was installed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 159216

Corrective Action: Clean up and remove stained soils per Rule 912.a.  
Properly dispose of oily waste in accordance with 905.e.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 02/09/2022

Operator  
Comment: Location is under Remedial Project #21723. Stained soils have been removed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 159217

Corrective Action: Properly dispose of oily waste in accordance with 905.e.

Date: 11/12/2021

Response: CA COMPLETED

Date of Completion: 02/01/2022

Operator  
Comment: Oil stained soils within secondary containment were properly cleaned up and disposed of.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 159218

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 11/12/2021

Response: CA COMPLETED

Date of Completion: 02/01/2022

Operator  
Comment: Fencing is in place to prevent Livestock entry.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 159219

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 12/01/2021

Response: CA COMPLETED

Date of Completion: 03/01/2022

Operator  
Comment: Interim reclamation at the south side of the tank has been completed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 2/11/2025 4:30:06 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
404089782	FIR RESOLUTION SUBMITTED
404089795	Location Photos

Total Attach: 2 Files