

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404092658

Date Received:

02/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dolezal, Pat

970-332-3585

pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 698603030

Inspection Date: 01/14/2025

FIR Submit Date: 01/15/2025

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 303899

Location Name: JOE BROPHY-64N47W

Number: 14SESE

County: YUMA

Qtrqtr: SESE

Sec: 14

Twp: 4N

Range: 47W

Meridian: 6

Latitude: 40.308970

Longitude: -102.587290

FACILITY - API Number: 05-125-

-00

Facility ID: 253767

Facility Name: JOE BROPHY

Number: 8-14

Qtrqtr: SESE

Sec: 14

Twp: 4N

Range: 47W

Meridian: 6

Latitude: 40.308970

Longitude: -102.587290

CORRECTIVE ACTIONS:

1 CA# 201761

Corrective Action: Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).

Date: 11/02/2024

Response: CA COMPLETED

Date of Completion: 02/05/2025

Operator
Comment:

Replaced packing and bolts

ECMC Decision:

Date: 2/13/2025 11:49:17 AM

404092658	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Page 2 of 2