

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404098234

Date Received:

02/18/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Katz, Aaron

aaron.katz@state.co.us

Haverkamp, Curtis

curtis.haverkamp@state.co.us

QB Energy

ecmc.inspections@qb-energy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708905735

Inspection Date: 02/11/2025

FIR Submit Date: 02/12/2025

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 334951

Location Name: HILL-67S92W

Number: 16NWNE

County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 16 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.450390 Longitude: -107.670660

### FACILITY - API Number: 05-045-

-00

Facility ID: 334951

Facility Name: HILL-67S92W

Number: 16NWNE

Qtrqtr: NWNE Sec: 16 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.450390 Longitude: -107.670660

### CORRECTIVE ACTIONS:

1 CA# 202516

Corrective Action: The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.

Date: 03/04/2025

Response: CA COMPLETED

Date of Completion: 02/13/2025

Operator Comment: Repaired liner.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 202517

Corrective Action: Comply with CECMC wildlife rules

Date: 02/19/2025

Response: CA COMPLETED

Date of Completion: 02/13/2025

Operator  
Comment: Covered flowline insulation opening.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed: \_\_\_\_\_

Title: Compliance

Date: 2/18/2025 3:09:55 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404098247	Covered flowline insulation.
404098275	Liner repaired.

Total Attach: 2 Files