

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403979496

Date Received:
02/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------|-------|------------------------------------|
| TEP | | COGCCInspectionReports@terraep.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302860
Inspection Date: 10/03/2024 FIR Submit Date: 10/04/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334884

Location Name: FEDERAL-67S96W Number: 4SENE County:
Qtrqtr: SENE Sec: 4 Twp: 7S Range: 96W Meridian: 6
Latitude: 39.467629 Longitude: -108.106436

FACILITY - API Number: 05-045- -00 Facility ID: 334884

Facility Name: FEDERAL-67S96W Number: 4SENE
Qtrqtr: SENE Sec: 4 Twp: 7S Range: 96W Meridian: 6
Latitude: 39.467629 Longitude: -108.106436

CORRECTIVE ACTIONS:

1 CA# 199313

Corrective Action: Secure equipment to comply with Rule 608.e. Date: 10/11/2024

Response: CA COMPLETED Date of Completion: 10/17/2024

Operator Comment: Lines on separator have been plugged. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

2 CA# 199314

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/19/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Location and access road have been bladed/graded to repair rills and increase stabilization. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA# 199313: Lines on separator have been plugged. Corrective Action complete.
CA# 199314: Location and access road have been bladed/graded to repair rills and increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 2/20/2025 8:50:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|--------------------------|
| 403979496 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files