

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2025

Submitted Date:

02/20/2025

Document Number:

715501330

FIELD INSPECTION FORM

Loc ID 315548 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Contact Information:

Contact Name	Phone	Email	Comment
Saint, John		jsaint@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Christian, Cody		Cody.Christian@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231019	WELL	AC	06/01/2023	OBW	103-08688	CHEVRON FEE 128X	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Thursday, 02/20/2025, Inspector Kirby Burchett, was on location to witness a 5 yr Mechanical Integrity Test to maintain Shut In/TA status at Scout Energy Management LLC on the Chevron Fee 128X well, Location #315548, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Surf Csg – 0 psi, Prod Csg – 0 psi, Tbg – 0 psi
Pressure up Production csg to 365 psi (400 psi gauge), Surf – 0 psi, Tbg – 360 psi
Hold for 15 minutes with a 7 psi pressure loss on gauge
Test charted with a 14 psi pressure loss

No follow up inspection is required.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-3700		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:			Date:		
Type: Bradenhead	# 1				
Comment:					
Corrective Action:			Date:		
Type: Other	# 1				
Comment:	Wellhead tree				
Corrective Action:			Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 231019 Type: WELL API Number: 103-08688 Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Surface csg ISIP – 0 psi, Tubing ISIP – 0 psi, Production csg ISIP – 0 psi
Pressure Production csg to 365 psi on a 400 psi gauge
Test for 15 min, Surf csg – 0 psi, Tubing – 360 psi
5 min – 360 psi, 10 min – 359 psi, 15 min - 358 psi
Chart recorder showed a 14 psi pressure loss

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501332	Form 21 (field)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6928063
715501333	Chart	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6928064