

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/29/2025

Submitted Date:

02/19/2025

Document Number:

707603671

FIELD INSPECTION FORM

Loc ID 434745 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434745	LOCATION	AC			-	State North Platte O-26 Pad	AO

General Comment:

This is a LOCATION inspection.
Well(s): 13: Producing | PR.
Battery: Active.

Centralized Battery serves 12 Location IDs
(432636, 434745, 429060, 310744, 433511, 454278, 432395, 441915, 434121, 332135, 445363, 470863).
(Well(s): 85: Producing | PR; 13: Shut-In | SI).

Centralized Battery serves 1 Tank Battery Facility ID
(481579).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Location signage.		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unnecessary equipment at Location site. See North side of Location site. Unnecessary equipment includes: Frac tank w/ spill pad. Refer to Rule 606 for guidance.		
Corrective Action:	*Remove unnecessary equipment from Location site. Comply with Rule 606. Corrective Action date: 03/21/2025. (30 days). See photo(s) #1, 2, 3. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: <u>03/21/2025</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 434745 Type: LOCATION API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Comment: <input style="width:90%;" type="text"/>						
Corrective Action: <input style="width:95%;" type="text"/>					Date: <input style="width:15%;" type="text"/>	
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 01/29/2025 at approximately 12:50 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: State North Platte/O-26 Pad Location ID: 434745 Well Name(s) & API: Reference: **FIR document #707603615, dated 01/29/2025. Location County: Weld County, Colorado Weather: Mostly Sunny, damp w/ snow patches from prior storm.</p> <p>While there, I observed: Well(s): 13: Producing PR. Battery: Active.</p> <p>**CORRECTIVE ACTION(s) COMMENT: During this inspection the following possible compliance issue(s) were observed: 1.) Unnecessary equipment at Location site. See North side of Location site. Unnecessary equipment includes: Frac tank w/ spill pad. Refer to Rule 606 for guidance. *Remove unnecessary equipment from Location site. Comply with Rule 606. Corrective Action date: 03/21/2025. (30 days). See photo(s) #1, 2, 3. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/19/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404099871	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6926187

707603672	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6926183
-----------	---------------	---