

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

02/26/2025

Document Number:

708303508**FIELD INSPECTION FORM**Loc ID 335313 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262936	WELL	PR	12/01/2010	GW	045-08076	CHEVRON GM 34-20	PR
268847	WELL	PR	03/16/2004	OW	045-09302	CHEVRON GM 334-20	PR
268849	WELL	PR	06/26/2003	OW	045-09303	CHEVRON GM 434-20	PR

**General Comment:**[CECMC Inspection Report Summary](#)

On 2/24/2025 at approximately 12:15, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE at Location ID #335313 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

- 1) Weathered wellhead sign
- 2) Open wellhead cellars
- 3) Stormwater; refer to Stormwater section

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Weathered wellhead sign at GM 434-20.		
Corrective Action:	Replace sign to comply with Rule 605.d.	Date:	03/29/2025
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970)285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Open wellhead cellars pose a safety threat.		
Corrective Action:	Cover wellhead cellars. 602.c: Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.	Date:	11/20/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		

Corrective Action:		Date:	
<b>Equipment:</b>		corrective date	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:	Date:		
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:	Date:		
Type: Bradenhead	# 3		
Comment:			
Corrective Action:	Date:		
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:	Date:		
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:	Date:		
Type: Dehydrator	# 1		
Comment:			
Corrective Action:	Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	262936	Type:	WELL	API Number:	045-08076	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	268847	Type:	WELL	API Number:	045-09302	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	268849	Type:	WELL	API Number:	045-09303	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Sediment Traps				
Berms						
Compaction						
Ditches						
		Ditches				
		Rip Rap				
		Gravel				
		Other	Fail			Insufficient erosion control
		Culverts				
Gravel						
		Compaction				

Comment: Insufficient erosion control; rill erosion cutting through access road to wellheads. No BMPs in place.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/14/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708303509	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936187">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936187</a>