

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
404113471

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:  
03/03/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Walker, Mandi</u>		<u>mwalker@hilcorp.com</u>
<u>.General</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001870  
Inspection Date: 02/24/2025 FIR Submit Date: 02/25/2025 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326584

Location Name: ALLISON UNIT-N32N7W Number: 24SESW County:  
Qtrqtr: SESW Sec: 24 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.002522 Longitude: -107.560768

FACILITY - API Number: 05-067-00 Facility ID: 326584

Facility Name: ALLISON UNIT-N32N7W Number: 24SESW  
Qtrqtr: SESW Sec: 24 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.002522 Longitude: -107.560768

CORRECTIVE ACTIONS:

1 CA# 202687

Corrective Action: Comply with rule 902. clean and remediate impacted soils to 915-1 cleanup concentrations. Additionally comply with rule 608.e. ensure mechanical integrity of well. Date: 03/25/2025

Response: CA COMPLETED Date of Completion: 03/03/2025

Cleaned and remediated impacted soils, see attached photos.

Operator Comment: \_\_\_\_\_

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 202688

Corrective Action: Comply with rule 605. Install or repair sign. Date: 03/25/2025

Response: CA COMPLETED Date of Completion: 03/03/2025

Operator Comment: Tanks are labeled, see attached photos.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 202689

Corrective Action: Comply with rule 1002f. Install or repair required BMPs. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 03/03/2025

Operator Comment: Road has been repaired, see attached photos.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech Date: 3/3/2025 2:00:22 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404113501	714001870_Resolved Photos

Total Attach: 1 Files