

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2025

Submitted Date:

03/03/2025

Document Number:

696307337

FIELD INSPECTION FORMLoc ID 436612 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Parrish, Melissa	970-397-3896	mparrish@fundareresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436612	LOCATION	AC			-	Horsetail 30 Production	AC

General Comment:

This is a Production Facility Field Compliance Audit

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at South Compressor		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unmarked OOSLAT Risers West of Heater Treaters and South of Compressors		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: VRT	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 8		
Comment:			
Corrective Action:		Date:	

Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: LACT	# 5		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL		400 BBLs	STEEL AST		,	
Comment:	32 Tanks					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	14	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	Candlestick Flare does not meet ECMC requirements for Enclosed Combustion	
Corrective Action:	Comply with Rule 903.(5)	Date: 06/06/2025

